FACTORY & FIELD WIRING



1. USE COPPER CONDUCTORS ONLY
2. UNIT MUST GROUNDED
3. FOR MOTOR AMPS SEE RATING STICKER ON OUTSIDE OF UNIT.

GRD = GROUND
FACTORY WIRING
FIELD WIRING

REV.	DESCRIPTION	DATE	BY
	REVISIONS		
G	DELETE UNITSTAT	3/24/06	HT
F	PURPLE WAS BLACK,YELLOW WAS BLUE,ORANGE WAS BLUE	7/7/06	BJ
E	T1,T2 WIRE ARRANGEMENT REVISED	5/15/05	BJ
D	ADD NOTE "FAN IS RUNNING ALL THE TIME	3/9/05	HT
C	REVISED WIRE COLORS TO AGREE WITH MOTOR MANUFACTURER	2/22/05	BJ
B	REWIRING SO THAT THE FAN IS ON ALL THE TIME	6/18/04	HT
A	INITIAL RELEASE	9/13/03	GA

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF LRC COIL CO. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF LRC COIL CO. IS PROHIBITED.

NEXT ASSY | USED ON

APPLICATION

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES
TOLERANCES ARE:
FRACTIONS DECIMALS ANGLES
+ .XX+ .XX + 1
.XXX+.XXX

MATERIAL XX

FINISH --

DO NOT SCALE DRAWING

CAD GENERATED DRAWING, DO NOT MANUALLY UPDATE

APPROVALS	DATE
DRAWN GA	9/13/2003
CHECKED	
RESP ENG	
MFG ENG	
QUAL ENG	

LRC COIL CO.

WIRING DIAGRAM
FOR HS-25 & HS-31
NO UNISTAT

SIZE A | DWG. NO. 17746-ED | REV. G
SCALE | CAD FILE: | SHEET OF