


FACTORY & FIELD WIRING



1. USE COPPER CONDUCTORS ONLY
2. UNIT MUST GROUNDED
3. FOR MOTOR AMPS SEE RATING STICKER ON OUTSIDE OF UNIT.

GRD = GROUND
 FACTORY WIRING ———
 FIELD WIRING - - - - -

REV.	DESCRIPTION	DATE	BY
E	ADD 3 WIRES (CFM MOTOR HAVE SIX WIRES)	1/26/07	HT
D	DELETE UNISTAT	3/24/06	HT
C	BLACKFROM MOTOR WAS BLUE	3/3/06	HT
B	T1,T2 WIRE ARRANGEMENT REVISED	5/15/05	BJ
A	INITIAL RELEASE	9/13/03	GA

REVISIONS	APPLICATION	USED ON

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ARE: FRACTIONS DECIMALS ANGLES + .XX+ .XX + 1 .XXX+.XXX		CAD GENERATED DRAWING, DO NOT MANUALLY UPDATE	
APPROVALS		DATE	
DRAWN	HT	2/22/2005	
CHECKED			
MATERIAL		RESP ENG	
XX			
FINISH		MFG ENG	
--			
NEXT ASSY		QUAL ENG	

LRC COIL CO.

**WIRING DIAGRAM
 FOR HS47,66,87,103,120
 NO UNISTAT**

SIZE A	DWG. NO. 17746-05	REV. E
SCALE	CAD FILE:	SHEET OF

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF LRC COIL CO. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF LRC COIL CO. IS PROHIBITED.